<u>.</u> S	Sanitized Copy Approved for Release 2011/10/14 : CIA-RDP82-00- CENTRAL IN <b>GUNTUE NUMBER</b>	457R001900460002-3 <u> </u>	50X1-HUM
	INFORMATISECRET PORT		
THTRY	Germany (Russian Zone)	DATE DISTR. 72 Octobe	or 1948
BJECT	Shortage of Railroad Repair Materials	NO. OF PAGES 2	·•
ACE QUIRED	/ (V)	NO. OF ENCLS.	
EOP I		SUPPLEMENT TO REPORT	50X1-HUM
DOCUMENT C	CONTAINS INFORMATION AFFECTION THE NATIONAL DEFENSE BY THIS IS UNEVALUATED INFO.  22. AS ABEGGED. 13' TRANSHISSION OR THE REVELATION BY THE STREET BY THE ST		ARCH
ED BY LAW.	THE ARY MANNER TO AN UNAUTHORIZED PERSON IS PRO- REPRODUCTION OF THIS FORM IS PROUBLED. HOW- OR CONTAINED IN BODY OF THE FORM ARY BE UTILIZED ISSARE BY, THE RECEIVING ACENCY.	NTELLIGENCE ANALYSTS	50X1-HUN
7.	The following materials are very nearly completely or railroad repair shops of the Soviet Zone of Germany:	ut of stock in the	
	a. <u>Frofiles</u> : NP 14, NP 20, NP 31. As an emergency steels such as double "I" profiles and "Flachelse cogether to form "U" profiles and single irons.	measure, constructional an <sup>n</sup> are being welded	
	b. Rivets, nails, nuts and bolts, and screws: Stocks are nearly exhausted. Emergency measures taken by Reichsbahn-Ausbesserungswerk Magdeburg will only suffice to supply two or three workshops. Axle steel or hoop-iron are used as raw materials.		
	wheel rims: lacking for locomotives of Series 38, 41 and 44. For series 52 a few are in stock. Those of the 720-750 measurement for passenger coaches are not available.		
	d. Tubes: Since the cessation of supplies from the so small that only those locomotives can be repair are available.	West, deliveries are red for which stocks	
€.	Glass and timber requirements can be covered from the zone. Timber stocks are low (average 1,000 to 2,000 cu. meters), and there is a deficiency of hard woods such as oak.		
9.	Dyes are short, but this is largely due to the "regionalism" of the Lander and a lack of sufficient central control.		
ls e	The lack of centralized control has resulted in stocks of scrap iron, despite instructions to the contrary, still being removed from the Branden-burg-West and Magdeburg repair shops, in accordance with the scrap iron collection drive.		
5,	Since the interruption of communications with the Wes situation regarding tires for locomotives in the rail: has become increasingly critical. The DWK was inform on 12 July that if tires and valves with a diameter of be obtained immediately, all repairs on locomotives with	road repair workshops ed by the railroads of 51 mm and 54 mm coun	ot
	CLASSIFICATION SECRET/CONTROL-U.S. OFFICIAL	LS ONLY	<del></del> 1
STATE #	X AIR X	1  , <sub>1</sub> , <sub>2</sub>	
STATE #		ment No.	
	NO C	CHANCE in Class.	50X1-HUM

Sanitized Copy Approved for Release 2011/10/14: CIA-RDP82-00457R001900460002-3

SECRET
CENTRAL INTELLIGENCE AGENCY

i.	2	₩	50X1-HUM

It will no longer be possible to admit locomotives requiring tubes of those sizes to the workshops.

E,

It is not thought likely that deliveries from Poland and Czechoslovakia of the materials in question can be expected at an early date. Hungary has, however, offered to repair German rolling stock, especially passenger coaches, and possibly also locomotives. Costs of Hungarian repairs, which appear to be reasonable, would be based on payment in dollars. Scrap iron would also be acceptable in lieu of dollar payment. Permission, however, must be obtained from General Kvashnin, head of the SMA Transport Division, for the German railroads to effect payment abroad by deliveries of scrap iron, in view of the material shortage in the Soviet Zone. On the other hand, the price estimates made by the Hungarians for any timber which would have to be delivered by Hungary are so high that the offer may be refused for that reason alone.

SECRET/CONTROL-U.S. OFFICIALS ONLY

## **SECRET**